

1/44




FIG. 1

202290\*TF55001

2/44




FIG. 2

202290-11555007




FIG. 3

202290" TFS900T

4/44




FIG. 4

202290-155500T

5/44




FIG. 5

20/290" TFS50T

6/44




FIG. 6

202290-TFS90T

7/44




FIG. 7




FIG. 8

1005511.062702

8/44




FIG. 9




FIG. 10

202290 TTS500T  
1005511-062702



9/44




FIG. 11






FIG. 12

200201230105511

10/44



202290 TT5500T

11/44




FIG. 15

202290" TFGG00T




FIG. 16




FIG. 17




FIG. 18

20220901.TT55500T 10055511.062702

13/44




FIG. 19

202290" T55500T

14/44




FIG. 20

20/2290" TFS5500T

15/44




FIG. 21A




FIG. 21B




FIG. 22

202290" TT55500T

16/44




FIG. 23

202290 "T55500T



17/44




FIG. 24

202290" TTS500T

18/44




FIG. 25




FIG. 26

202290-11555001

19/44




FIG. 27




FIG. 28

20/290" TFS500T

20/44




FIG. 29

20/44




FIG. 30

21/44




FIG. 31

202290-155500T

22/44




FIG. 32




FIG. 33

23/44









FIG. 34

202290" TFS5500T

24/44



10055511.062702



25/44




FIG. 39

202290-155001

26/44




FIG. 40

202290" TTS500F

27/44




FIG. 41

2022910" TFS5500T

28/44






FIG. 42

1005511-062702

29/44



30/44



31/44




FIG. 45




FIG. 46

20220715 10:55:11.062703

32/44




FIG. 47A




FIG. 47B




FIG. 47C

202290-T55500T



33/44








FIG. 48

202290"TF55500F

34/44



35/44




FIG. 50A




FIG. 50B




FIG. 50C




FIG. 50D

204290"TF55500T

36/44




FIG. 51A




FIG. 51B

202501062702

37/44




FIG. 52

20250101 1055511

38/44




FIG. 53

10055511.062702

39/44




FIG. 54

10055511.062702

40/44




FIG. 55

10055511.062702



41/44




FIG. 56

20/290" FT55500T

42/44




FIG. 57A




FIG. 57B




FIG. 58A




FIG. 58B

1005511.062702

43/44




FIG. 59A




FIG. 59B




FIG. 59C

20220711 10:55:11

44/44




FIG. 60A




FIG. 60B

20220229-155500T